



Volume 2: Environmental Statement Further Information Report Figures

Brent Cross Cricklewood: Phase 1B (North) Reserved Matters Application

May 2017

Waterman Infrastructure & Environment Limited


Pickfords Wharf, Clink Street, London SE1 9DG
www.watermangroup.com

Client Name: Brent Cross Cricklewood Development Partners
Document Reference: WIE11453-100 ES FIR Volume 2 Figures
Project Number: WIE11453-100

Quality Assurance – Approval Status

This document has been prepared and checked in accordance with
Waterman Group's IMS (BS EN ISO 9001: 2008, BS EN ISO 14001: 2004 and BS OHSAS 18001:2007)

Issue	Date	Prepared by	Checked by	Approved by
First	06/04/17	Neil Purvis	Mairead Rawal	Ruth Martin
Second	10/05/17	Neil Purvis	Mairead Rawal	Ruth Martin



Disclaimer

This report has been prepared by Waterman Infrastructure & Environment Limited, with all reasonable skill, care and diligence within the terms of the Contract with the client, incorporation of our General Terms and Condition of Business and taking account of the resources devoted to us by agreement with the client.

We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above.

This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies on the report at its own risk.

Content

Figure 1.1: Site Location

Figure 1.2: Planning Boundary of 2014 Permission

Figure 2.1: Phase 1B (North) Development

Figure 2.2: Development Zones

Figure 2.3: Proposed Areas of Demolition of the Existing Shopping Centre

Figure 4.1: Location of Cumulative Schemes

Figure 5.1: Existing Land Uses

Figure 7.1: Phase 1B (North) Construction Access Routes

Figure 7.2: Predicted Construction HGV Volumes

Figure 7.3: Predicted Construction LGV and Private Vehicle Volumes

Figure 9.1: s73 ES noise monitoring locations and the 2014 baseline noise monitoring locations

Figure 10.1: Visual and Terrain Analysis

Figure 10.2: Existing Open Space on Site

Figure 10.3: Approximate Extent of Tree Preservation Order Area

Figure 10.4: Townscape Character Areas

Figure 10.5: Viewpoint Locations

Figure 11.1: Extended Phase 1 Habitat Survey Plan

Figure 11.2: Proposed Green / Brown Roofs

Figure 11.3: Tree Retention and Loss Plans

Figure 13.1: Areas Identified for Archaeological Mitigation in Phase 1B North

Figure 14.1: Diffusion Tube Monitoring Locations

Figure 14.2: Assessment Receptor Locations

Figure 14.3: Ground Level NO_x Concentrations

Figure 15.1: Ground Investigation Plan

Figure 15.2: Groundwater Level Plan

Figure 15.3: Ground Contamination Findings Plan

Figure 17A.1: Configuration 2: Phase 1AN and 1BN with Illustrative Surrounds (Ground Level)

Figure 17A.2: Configuration 2: Phase 1AN and 1BN with Illustrative Surrounds (Plot 113 at Balcony Level)

Figure 17B.1: Location of Residential Receptors surrounding Phase 1B (North)

Figure 17B.2: Location of Phase 1B (North) External Amenity Areas Assessed

Figure 17B.3: Phase 1B North Internal Pedestrianised Areas Assessed for Daylight Availability